



ESTB
SWEET KLEEN LAUNDRY
1925



Sweet Kleen Laundry pre-demolition building conditions





Chimney dismantling at site.



Cleanup operations at the site.






Abandoned drums within site buildings,
prior to removal.

Site conditions prior to EPA cleanup



Asbestos in buildings,
prior to abatement.



Asbestos pipe wrap

The photograph shows a close-up of a building's interior, likely a basement or crawlspace. A light-colored, textured pipe is visible, wrapped in a dark, fibrous material identified as asbestos pipe wrap. The pipe is surrounded by wooden framing and other pipes. Three white arrows point to different areas of the pipe wrap, indicating the presence of asbestos. The overall scene is dimly lit and shows signs of age and decay.

Installation of passive soil vapor extraction system



Passive SVE system post-restoration



16 4:57PM


Perchloroethylene contaminated soils excavated and staged for disposal.




Removal of concrete slabs from
perchloroethylene contaminated soil
excavation area.



Perchloroethylene contaminated soil excavation area



Location of perchloroethylene
contaminated soil prior to excavation.



Sweet Kleen Laundry pre-demolition building conditions

